SOUTH PRODUCTION NOTES

December 27-28, 2014 3-11, 11-7, 7-3 Shift Notes

BASF EMPLOYEES
67 Last Recordable
547 Last Lost Time

Be sure to check weigh all bags off of the calciners and fill out the log sheet downstairs by the scale and Attach "Packaged By" label with your initials.

#1 MED / AL 4126 1/16th done, Al 3945 next:

Should be done. Need to calcine and ensure we complete lot 45 (20 bags) on calciner

For Afternoon shift: Mixer was cleaned out, continue cleaning pulva and extruder (rough clean), lock out dryer for quick cleaning (Piechuta)

For Midnight shift: Hold

For Day shift: Hold

#1 RC /AL 4126 1/16th done, Al 3945 next:

Continue

For Afternoon shift: Should be finishing last of the 4126. Bring calciner down

and reverse, then hold

For Midnight Shift: Hold (see above)

For Day shift: Hold (see above)

Exhaust to Trimer

#2 MED line / Cu-0860:

Continue, get all samples to sample shelf end of each shift. Be sure to use wet mix on every batch. Dry ice tote was delivered to warehouse when needed. For Afternoon Shift: Continue. DO NOT USE ANY LOT 476 of Cu 3818 (World Metals) in powder room

For Midnight shift: Continue. DO NOT USE ANY LOT 476 of Cu 3818 (World

Metals) in powder room

For Day Shift: Continue. DO NOT USE ANY LOT 476 of Cu 3818 (World Metals)

in powder room

#2 RC/ Cu 0860:

Continue. Bladder on bag off station should be working now. Still need to feed bags on 1st floor (Bodmann will advise)

For Afternoon Shift: Continue For Midnight shift: Continue

For Day Shift: Continue

Exhaust to F1

#3 MED/ D-1780 LAQ:

Repairs to solids hopper vibrator Saturday. Will restart when they are done.

Door seals have been replaced.

For Afternoon Shift: Restart line, continue

For Midnight shift: Continue For Day Shift: Continue

#3 RC / D 1780 LAQ:

Continued on and off depending on feed availablility. We will need to get to Lot 28 bag 11 off the Calciner, then contact Bodmann before switching to 1780

NAQ. Screener skimmed over, installed Cleaning kit.

For Afternoon Shift: Continue For Midnight shift: Continue For Day shift: Continue

Exhaust to CTO

#4 RC / 5202:

Continued to feed. Have been running with a discharge rate around 400 without any leaks. Many attempts have been made to run above 600, but the feed end has leaked every time.

For Afternoon Shift: Continue For Midnight shift: Continue For Day Shift: Continue

Exhaust to 4DC

#5 RC / Cu-3818:

Running 3818 again. Make sure temps are correct and follow MOD. Make sure we are keeping the feed hopper filled, it is affecting the SA for this product because we are not getting consistent feed rates.

For Afternoon shift: Continue For Midnight Shift: Continue For Day shift: Continue

Exhaust to 5DC

#6 RC & Dryer / D-0257

Use Auto Sampler for bags, and get additional grab sample for each bag. For Afternoon shift: Continue, keep feed rate on high end (~250 lbs/hr) For Midnight shift: Continue, keep feed rate on high end (~250 lbs/hr) For Day Shift: Continue, keep feed rate on high end (~250 lbs/hr)

Exhaust to Sly Scrubber

6 Tank /D-5253 empty

Continue. Drain looked at by Schirmer and Lucas- not fixed yet

For Afternoon shift: NA

For Midnight Shift: no activity

For Day Shift: No activity

New Pfaudler / D 5253 done

Pfaudler glass was inspected.

For Afternoon Shift: NA

For Midnight Shift: No change.

For Day Shift: No activity

7 Tank AMT, KLP solution next?

Hold Eliott advised that radar gauge on tank is not working. Will need repaired.

For Afternoon shift: NA For Midnight Shift: NA

For Day Shift: NA

Old Pfaudler / D-0257:

Continue, rental DI water unit delivered and installed on Saturday for pfaudler and #3 mixer. You will not be able to pump the water using the RO unit pump...water will deliver by city water pressure, so it will be slower.NOTE: Be sure to sample drainage from each batch made on east pfaudler for D 0257 batches.

For Afternoon shift: Hold until midnight

For Midnight Shift: Continue For Day Shift: Continue

National Dryer:

Schirmer finished bead blasting.

For Afternoon Shift: NA For Midnight Shift: NA

For Day shift: NA

PK Blender/X 1000 repacks:

PK Clean and ready for repacks

For Afternoon shift: Hold until Monday

For Midnight Shift: holding for modifications to pk

For Day shift: Should be ready to start repacks on Monday afternoons maybe

Abbe Blender / 5206 Done

Done for a while. Area Cleaned

For Afternoon shift: NA For Midnight shift: NA For Day shift: NA

Tower 3/ Cu 0860:

Will load and start on Midnight Friday

For Afternoon shift: Continue For Midnight Shift: Continue For Day shift: Continue

Tower 6 / Pd 1930:

Waiting on Pd 1930 material for repacking...schedule as needed before each tower load. Reuse drums, if drums are in good condition, black out labels with spray paint and put new label on drum. 30 drum tower loads.

For Afternoon shift: Hold For Midnight Shift: Hold For Day shift: Hold

North Screener / Cu-0860:

Continue. Keep running, WOW for leaking Pump

For Afternoon shift: Hold For Midnight shift: Hold For Day shift: Hold

South Screener / Cu-0860:

Continue. Keep running, WOW for leaking Pump

For Afternoon Shift: Hold For Midnight shift: Hold For Day shift: Hold

#2662 (west) Pill Machine / Al-3915 T 5/32:

Running, when able.

For Afternoon shift: Continue For Midnight shift: Continue For Day Shift: Continue

#2664 (east) Pill Machine / Al-3915 T 5/32:

Running, when able.

For Afternoon shift: Continue For Midnight shift: Continue For Day Shift: Continue

TK #2 / V 2046/V 2010:

Down for now. Will need to be switched to V-2010 Saggers...will discuss next

week

Afternoon shift: Down For Midnight shift: Down For Day Shift: Down

TK #4 / Cu 2508 next:

Work completed at kiln building, relighting

For Afternoon shift: Bringing temps back up, feed when ready For Midnight shift: Bringing temps back up, feed when ready For Day Shift: Bringing temps back up, feed when ready

Harrop Kiln / Al 3920:

Al 3920 - 90 min Cart- operator must keep area cleaned

For Afternoon shift: Continue For Midnight shift: Continue

For Day Shift: Continue

Building 27 Belt Filter / 5020:

Cu-5020. Maintenance looked at recycle pump on 107 and it appears that the lines are getting clogged by the material soda ash and britesorb solution and causing the pump to kick out on low limit because it runs dry, do not continue to reset the pump if you have this issue, running it dry will damage the pump.

For Afternoon Shift: Down, blower motor bearings need replaced For Midnight shift: Down, blower motor bearings need replaced

For Day shift: Down, blower motor bearings need replaced

Priorities:

Priorities 1 through 12 are basically all the same priority, should be considered urgent and will require call outs for maint issues and/or processing issues.

- 1) East Pfaudler/HC-11 Dryer/#6 RC/Sly
- 2) #3 MED/#3RC/CTO
- 3) #2 Line/#2RC
- 4) Harrop Kiln
- 5) Horne Tabletting
- 6) #1 Line/#1RC
- 7) South PK (NA Selexsorb)
- 8) South Precip
- 9) #5 RC
- 10) Reduction Towers
- 11) Reduction Tower Screeners
- 12) #4 RC
- 13) #4 Tunnel Kiln

Al-3915 and Al-3920 continue to move up the list, we are projecting to be late to our commitment to Seneca in delivering the AL-3920 by year end.

In reviewing their plan, we can be ~1 week late at most before it affects them, which in turn affects when the material returns for reduction, which places the burden on us to still meet the QVAM ship date.

Projected end date on the Al-3920 T is showing as Jan 6th.

Maintenance & Other

- 1) Belt filter down for blower bearing replacement
- 2) MOC for PK bottom outlet for X-1000 repacks Monday
- 3) Rental DI water unit is installed. You will only have city water pressure on the 3rd floor, so transfers to #3 mixer weigh tank and east pfaudler will be slower than normal
- 4) Shirmer power-washing in building 10 completed, #4 Tunnel Kiln heating back up

Shipments to finish for December